

**SPECIFICATION AMENDMENTS:**

Please replace the paragraph on page 4, lines 6 through 14, with the following amended paragraph:

--The top member 20 is substantially mating the bottom member 10 and covers the bottom member 10. The top member 20 has notches 21 formed on the sidewalls corresponding to where the connectors 40 are located. The top member 20 further has a plurality of round openings 22 of various sizes corresponding to indication lights (not shown in the drawings), and a pair of elongated troughs 23 corresponding to where the keyboard (not shown in the drawings) is mounted. There is also a plurality of rectangular troughs 24 corresponding to the touch panel 70. In addition, the top member 20 has a pivot seat 25 on one side to enable a LCD device ~~(not shown in the drawings)~~ 80 to be coupled thereon in a turning manner.--